


Schraube am Motor montiert

BOLT IS REMOVED FROM CORNER
OF ENGINE HSG THEN REINSTALLED
WITH THE CABLE GUIDE IN PLACE.



E4-01383A-01