



|             |             |
|-------------|-------------|
| YM 6021 SPK | 12A-377D643 |
| GES 53      | 12A-378R678 |
| GES 53 H    | 12A-378Q676 |
| CPG 53 BM   | 12A-378R641 |
| CPG 53 HM   | 12A-379Q641 |
| 530 HM      | 12A-378S689 |
| HB 53 RLSK  | 12A-377D690 |
| HB 53 RB    | 12A-378E690 |
| HB 53 RB    | 12A-378R690 |
| 53 HA       | 12A-378Q621 |
| 478 SP      | 12A-378R611 |
| RB 53-5R    | 12A-378R628 |
| HB53RT      | 12A-373N690 |
| 53SP        | 12A-378R622 |
| GES53H      | 12B-378S678 |
| GES53H      | 12A-379Q602 |
| SILVER 530K | 12A-377D677 |




YM6021 SPK ,  
HB53RT ,  
HB53RLSK ,53HA ,  
HB 53 RB (12A-378R960)  
RB53-5R  
  
CPG 53 HM ,12A-379Q641  
GES53H ,12A-379Q602

### 31 TEC-Motor

HB53RT

### 30 KAWA-Motor

YM6021 SPK , HB53 RLSK ,  
SILVER 530K



### 29 B&S-Motor

RB 53-5R , 53SP ,  
HB53 RB (12A-378R690)

### 28 B&S-Motor

GES53 ,CPG53BM ,  
478 SP ,  
HB53RB (12A-378E690)

### 27B Honda-Motor

GES 53H ,12A-379Q602

### 27A Honda-Motor

53HA , GES 53H ,12A-378Q676


### 27 Honda-Motor

530HM  
GES53H ,12B-378S678

### 26 Honda-Motor

CPG 53 HM

nicht abgebildet  
not shown



E3-02540B-01